UNCLASSIFIED

AD NUMBER AD918677 **LIMITATION CHANGES** TO: Approved for public release; distribution is unlimited. FROM: Distribution authorized to U.S. Gov't. agencies only; Test and Evaluation; JAN 1974. Other requests shall be referred to Air Force Rocket Propulsion Lab., Edwards AFB, CA. AUTHORITY AFRPL ltr 13 May 1966

THIS REPORT HAS BEEN DELIMITED

AND CLEARED FOR PUBLIC RELEASE

UNDER DOD DIRECTIVE 5200,20 AND

NO RESTRICTIONS ARE IMPOSED UPON

ITS USE AND DISCLOSURE.

DISTRIBUTION STATEMENT A

APPROVED FOR PUBLIC RELEASE;
DISTRIBUTION UNLIMITED.

AD 918 677

AUTHORITY:
AFRPL etc.,

13 May 860





DEVELOPMENT OF LARGE DIAMETER HIGH CHAMBER PRESSURE THROAT INSERT MATERIALS

Volume III
Vapor Deposition of Pyrolytic
Graphite Coatings For Large
Diameter Throat Inserts

Final Report
Contract FO 4611-70-C-0009

Period Covered
15 February 1970 to 1 September 1972

Author:

Kenneth E. Undercoffer

1974

AFRPL-TR-72-112

APR 16 1974



Prepared by:

ATLANTIC RESEARCH CORPORATION
5390 CHEROKEE AVE.
ALEXANDRIA, VIRGINIA 22314

AIR FORCE ROCKET PROPULSION LABORATORY
DIRECTOR OF SCIENCE AND TECHNOLOGY

Air Force Systems Command Edwards, California

UNCLASSIFIED
SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION F	AGE	READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	. GOVT ACCESSION NO.	S. RECIPIENT'S CATALOG NUMBER
AFRPL-TR-72-112		
4. TITLE (and Subtitle)		5. TYPE OF REPORT & PERIOD COVERED
Development of Large Diameter High-Chamber Pro Materials.	essure Throat Insert	Final - 15 February 1970 to 1 September 1972
Volume III - Vapor Deposition of Pyrolytic Grap	hite Coatings for	6. PERFORMING ORG. REPORT NUMBER
Large Diameter Throat Inserts 7. AUTHOR(s)		42-5489 8. CONTRACT OR GRANT NUMBER(*)
Kenneth E. Undercoffer		F04611-70-C-0009
9. PERFORMING ORGANIZATION NAME AND ADDRESS		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
Atlantic Research Corporation		BPSN: 623059
5390 Cherokee Avenue Alexandria, Virginia 22314		Project No.: 3059
11. CONTROLLING OFFICE NAME AND ADDRESS		Prog. Elem. No: 6.23.02F
Air Force Rocket Propulsion Laboratory		January 1974
Director of Laboratories		13. NUMBER OF PAGES
Edwards, CA 93523; Air Force Systems Command		105
14. MONITORING AGENCY NAME & ADDRESS(II different	from Controlling Office)	15. SECURITY CLASS. (of this report)
Commander, DCASD Baltimore Building 22, Fort Holabird Baltimore, Maryland 21219		UNCLASSIFIED
battimore, maryland 21219		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report)		197.3
Distribution limited to U.S. Government agencies of requests for this document must be referred to AF 17. DISTRIBUTION STATEMENT (of the abstract entered in		
18. SUPPLEMENTARY NOTES		
19. KEY WORDS (Continue on reverse side if necessary and	identify by block number)	
Vapor Deposition Pyrolytic Graphite Coatings Rocket Nozzles		
20. ABSTRACT (Continue on reverse side if necessary and i	dentify by block number)	
Volume III — Describes the development of a procumith pyrolytic graphite. Inserts with throat diameters		

CURITY CLASSIFIC	ATION OF THIS PAGE(When	Dela Entered)	CTAPICINICS TOOKIN
			Companies of the Table State Commercial
		•	

TABLE OF CONTENTS

MINTALE STATES

				I	Page
		white the state of			
1	INT	RODUCTION			1
		Paper Country Coppin Learner for Europe Securit Deposition .			
11	OBJ	ECTIVE			1
		National tenth of Promption The Rate or Visiting			
Ш	SCO	PE			1
IV	CON	ICLUSION	٠.		2
v	CEN	United at COATING PROCEDURES			
V	GEN	IERAL COATING PROCEDURES	• •	• •	3
VI	COA	ATING DEVELOPMENT			11
	1.	7.0-INCH NOZZLE THROAT INSERTS			11
	2.	10.6-INCH NOZZLE THROAT INSERTS			54
	3.	13.0-INCH NOZZLE THROAT INSERTS			60
	4.	12.45-INCH NOZZLE THROAT INSERTS			76
VII	DISC	CUSSION			97
		Element Navade Threst than a substante	• • •	•	

Albin Distribution

Continued to the particle of the supplies to

LOSS A JOHnst Company of William A Million

Difference of the particular form the which a

Discrepting Competitions by High Next 600 5 Feed 63004

LIST OF ILLUSTRATIONS

Figure		Page
1	Large Nozzle Deposition Assembly	. 4
2	Water-Cooled Copper Injector for Large Nozzle Deposition	. 5
3	Relationship of Process Gas Flow Rate to Coating Surface Temperature (Coating thickness ~50 mils)	. 7
4	As Deposited 7,0-inch Throat Insert No. 6300-1 (Coating surface stains are superficial)	. 12
5	Coating Microstructure of 7,0-inch Throat Insert No. 6300-39, Entrance End View, X60	. 13
6	Coating Microstructure of 7.0-inch Throat Insert No. 6300-9, Exit End View, X60	13
7	Coating Microstructure of 7.0-inch Throat Insert No. 6300-32, Entrance End View, 135X	14
8	7.0-inch Nozzle Throat Insert Substrate Configurations 1 and 1A	23
9	7.0-inch Nozzle Throat Insert Substrate Configuration 2 (Including groove modifications)	24
10	7.0-inch Nozzle Throat Insert Substrate Configuration 3	25
11	7.0-inch Injector Tip Configuration 1 . ,	27
12	7.0-inch Injector Tip Configuration 2	28
13	7.0-inch Injector Tip Configuration 3	29
14	Deposition Chamber Geometry of Run No. 6000-1	30
15	Deposition Chamber Geometry of Run No. 6300-1	32
16	Deposition Chamber Geometry of Run No. 6300-2	33
17	Deposition Chamber Geometry of Run No's, 6302-3 and 6300-4	34

LIST OF ILLUSTRATIONS (continued)

Figure		Page
18	Deposition Chamber Geometry of Run No's 6300-5 and 6300-6	. 36
19	Deposition Chamber Geometry of Run No. 6300-7	. 37
20	Deposition Chamber Geometry of Run No. 6300-8	. 38
21	Deposition Chamber Geometry of Run No's 6300-9 and 6300-10	. 40
22	Deposition Chamber Geometry of Run No's 6300-11 thru 6300-16	. 41
23	Deposition Chamber Geometry of Run No's 6300-17 thru 6300-19 and Run No. 6300-30	. 42
24	Deposition Chamber Geometry of Run No. 6300-20	. 44
25	Deposition Chamber Geometry of Run No. 6300-21	. 45
26	Deposition Chamber Geometry of Run No. 6300-22	. 46
27	Deposition Chamber Geometry of Run No. 6300-23	. 47
28	Deposition Chamber Geometry of Run No. 6300-24	. 48
29	Deposition Chamber Geometry of Run No. 6300-25	. 49
30	Deposition Chamber Geometry of Run No. 6300-26	50
31	Deposition Chamber Geometry of Run No. 6300-27	. 51
32	Deposition Chamber Geometry of Run No. 6300-28	. 52
33	Deposition Chamber Geometry of Run No. 6300-29	53
34	Deposition Chamber Geometry of Run No. 6300-31	55
35	Deposition Chamber Geometry of Run No's 6300-32 thru 6300-45	56
36	10.6-inch Nozzle Throat Insert Substrate Configuration	. 59
37	Deposition Chamber Geometry of Run No. 7300-1	61

LIST OF ILLUSTRATIONS (continued)

Figure		Page
38	Deposition Chamber Geometry of Run No. 7300-2	62
39	Deposition Chamber Geometry of Run No. 7300-3	63
40	13,0-inch Nozzle Throat Insert Substrate Configuration 1	66
41	Deposition Chamber Geometry of Run No. 8300-1	67
42	Deposition Chamber Geometry of Run No. 8300-2	69
43	Deposition Chamber Geometry of Run No's 8300-3 and 8300-4	70
44	Deposition Chamber Geometry of Run No. 8300-5	71
45	Deposition Chamber Geometry of Run No's 8300-6, 8300-7 and 8300-8	73
46	Deposition Chamber Geometry of Run No. 8300-9	74
47	Deposition Chamber Geometry of Run No. 8300-10	75
48	Deposition Chamber Geometry Run No's 8300-11 and 8300-12	77
49	12.45-inch Throat Insert No. 8300-24, Entrance End View	
50	Coating Microstructure of 12.45-inch Insert	
	No. 8300-21, Entrance End, 60X	7 9
51	Coating Microstructure of 12.45-inch Insert No. 8300-21, Exit End, 60X	79
52	Injector Tip Configuration Utilized for Runs 8300-13 thru 8300-15	
	(Plenum diameter 0.343) and Runs 8300-16 thru 8300-18 (Plenum diameter as shown)	82
53	Injector Tip Configuration Utilized for Runs 8300-19 thru 8300-26	83
54	12.45-inch Nozzle Throat Insert Substrate Configuration 1 (Including groove modifications)	85
55	Deposition Chamber Geometry of Run No's 8300-13, 8300-15 (Mandrel removed) and 8300-16	87

LIST OF ILLUSTRATIONS (continued)

Figure		Page
56	Deposition Chamber Geometry of Run No. 8300-14	. 88
57	Deposition Chamber Geometry of Run No's 8300-17 and 8300-18 (Injector lowered 1/4 inch)	. 90
58	Deposition Chamber Geometry of Run No's 8300-19 (Mandrel position indicated by broken line), 8300-20 and 8300-21	. 91
59	Deposition Chamber Geometry of Run No. 8300-22	. 93
60	Deposition Chamber Geometry of Run No. 8300-23	. 94
61	Deposition Chamber Geometry of Run No's 8300-24, 8300-25 and 8300-26 (Injector lowered 1/4 inch)	. 95

LIST OF TABLES

Table	Page
1	Coating Index System
II	7.0-Inch Nozzle Throat Insert Deposition Conditions
111	7.0-Inch Nozzle Throat Insert Substrate and Coating Data
IV	7.0-Inch Nozzle Throat Insert Substrate Dimensional Changes After Coating
v	10.6-Inch Nozzle Throat Insert Deposition Conditions
VI	10.6-Inch Nozzle Throat Insert Substrate and Coating Data
VII	13.0-Inch Nozzle Throat Insert Deposition Conditions
VIII	13.0-Inch Nozzle Throat Insert Substrate and Coating Data
IX	12.45-Inch Nozzle Throat Insert Deposition Conditions
X	12.45-Inch Nozzle Throat Insert Substrate and Coating Data
ΧI	12.45-Inch Nozzle Throat Insert Substrate Dimensional Data
XII	Nominal Process Conditions for Large Nozzle Deposition Runs

SECTION I

INTRODUCTION

Techniques for the fabrication of pyrolytic graphite coated rocket nozzle components were developed by Atlantic Research for AFRPL under several prior contracts. During these programs pyrolytic graphite coated nozzle throat inserts were fabricated and test fired in throat sizes up to 2.3 inches. Electrode grade AGSR graphite was the established substrate material. The successful performance of these parts indicated that a scale-up in size was warranted to determine the suitability of the PG-coated AGSR system in larger sizes. This is Volume III of a three-volume report and contains a description of the deposition process development.

Volume I contains the analysis of the five 7.0-inch throat diameter test firings conducted at AFRPL.

Volume II describes the nondestructive testing of the PG-coated throat inserts, the design analysis of the 7-inch PG coated throat, and the design analysis of the 7-inch nozzle package. Also included are details of the nozzle fabrication and the post-firing analysis of the ablative components.

SECTION II

OBJECTIVE

The basic objective of this phase of the program was to develop techniques for the fabrication of pyrolytic graphite coated nozzle throat inserts with throat diameters of 7.0, 10.6, and 12.45 inches. Five 7.0-inch throat diameter inserts were to be fabricated for test firing at AFRPL.

SECTION III

SCOPE

Coating techniques were developed for the fabrication of nozzle throat inserts with throat diameters of 7.0, 10.6, 12.45, and 13.0 inches.

Very coarse-grained AGSR graphite was utilized as the basic substrate material. Five 7.0-inch-diameter nozzle throat inserts were fabricated and test fired.

SECTION IV

CONCLUSION

Large diameter pyrolytic graphite components can be fabricated using techniques established during this program. Reproducibility was demonstrated in the 7.0-inch size and, with a statistically significant number of runs, could probably be demonstrated in the larger sizes. Indications are that AGSR graphite is not an ideal substrate material for large diameter parts and other graphitic materials with lower coefficients of thermal expansion should be investigated as potential substrate materials.

SECTION V

GENERAL COATING PROCEDURES

The large nozzle deposition runs were conducted in a 20-inch diameter induction furnace, heated by a 100 kW, 10 kHz, Aj Motor Generator.

The graphite substrate to be coated was placed inside a graphite canister using contoured graphite fixtures to direct the deposition gases onto the substrate and out of the deposition chamber. A generalized view of the large nozzle deposition assembly is shown in Figure 1.

In most of the runs a contoured graphite mandrel was utilized to reduce the free volume within the center of the deposition chamber. Several different mandrel configurations were tried for each of the three substrate sizes. The initial mandrel designs utilized holes drilled in the base to pass the exhaust gases from the deposition chamber to the furnace exhaust tube. This system was unsatisfactory because the holes plugged during deposition. Slots were tried to increase the gas exhaust area but these also clogged. The problem was finally solved by setting the mandrel on one-half-inch-diameter posts.

Commercial grade methane was the carbonaceous gas and was diluted with nitrogen to 1.9-5.1 volume percent before introduction into the furnace. This gas enters the furnace through a water-cooled, multiple-holed injector, as shown in Figure 2. A small amount of nitrogen was introduced into the annular area around the injector to prevent back-flow of the gases between the injector and the graphite entrance section.

Deposition temperature was monitored on the canister backside with a Leeds & Northrop Model 8632F optical pyrometer and controlled manually by adjusting the power input from the motor generator.

Because deposition temperatures are routinely measured on the canister backside, the recorded temperature is less than the temperature of the deposition surface which determines the characteristics of the coating. This difference is caused by the cooling effect of the process gas on the coating surface and increases with coating thickness because of the low conductivity of the coating in the "c" direction.

For small substrates and low gas flow rates, this temperature difference is believed to be negligible. However, because of the increased gas flow rates used during fabrication of large nozzles, the thermal gradient, between the deposition surface and the outside surface of the deposition chamber, becomes significant. To determine the magnitude of this gradient, a previously coated 7.0-inch nozzle (55 mils of PG at throat) was assembled using the deposition chamber geometry established for the last fourteen runs of the 7.0-inch series. Two holes were drilled through the deposition chamber and into the coating at the nozzle throat plane. The first penetrated the canister, substrate and coating to within 5 mils of the coating inner surface. The second penetrated the canister and the substrate to the substrate/coating interface. A second sight tube was added to the furnace, which lined up with these holes. The previously used sight tube plane was 6 inches above the substrate throat plane. The furnace was then heated to deposition temperature. Temperatures were recorded at the substrate throat plane, 5 mils from the coating surface, at the substrate/coating interface, and on the canister backside. The canister backside temperature was also recorded using the original sight tube.




Figure 1. Large Nozzle Deposition Assembly.




Figure 2. Water-Cooled Copper Injector for Large Nozzle Deposition.

Measurements were made at five different nitrogen gas flow rates, the highest of which was that used for Runs 6300-32 through 6300-45. Methane was introduced for a brief period, at the highest of the gas flow rates, to determine its cooling effect. The methane addition lowered the coating surface temperature approximately 20°F, immediately upon introduction. Its exact effect on the thermal gradient could not be determined because if the flow was maintained for an extended period, the PG thickness would have increased significantly.


An average canister backside temperature decrease of 30°F was measured between the new sight tube, installed at the throat plane, and the original sight tube 6 inches above, indicating that the upper part of the deposition chamber runs slightly lower in temperature than the middle.

The thermal gradient between the coating surface and the coating interface averaged about 90°F. This indicates that the temperature should be slowly increased by this amount during the run to maintain a constant temperature at the coating surface.

The overall thermal gradient between the coating surface and the deposition chamber backside varied with the nitrogen flow rate as shown in Figure 3.

These data show that for a starting temperature reading of 4100°F on the canister backside, and with the temperature slowly increased to 4200°F throughout the run, the deposition surface temperature will be 3800°F. This procedure was used for all 7.0-inch deposition runs after 6300-37 and all 12.45-inch deposition runs after 8300-22.

A coating index system was utilized to define the type of part fabricated and the major coating characteristics. This is shown in Table I. For cataloging purposes, the parts were given sequential numbers based on the first 2 digits only. A second series of numbers denotes the deposition log book number. An example of the system as used in this report is:






Figure 3. Relationship of Process Gas Flow Rate to Coating Surface Temperature (Coating thickness \sim 50 mils).

Table I. Coating Index System.

		Di	git	
Description of Part	1 st	2nd	3rd	4th
NOMINAL SIZE				
7.0	6			
10.0	7			
13.0	8			
SHAPE				
Cylindrical		0		
Standard Insert		3		
Wraparound — Large Radius		4		
Wraparound — Small Radius		5		
Entrance Approach		7		
Exit Section		9		
NOMINAL COMPOSITION				
Pyrolytic Graphite (Unalloyed)			0	
8% SiC			1	
15% SiC			2	
25% SiC			3	
Graded Coating			5	
NOMINAL THICKNESS (mils)				
50 (0/75)				0
100 (75/125)				2
150 (125/175)				4
200 (175/250)				6
250 and Beyond	۵			8

Volumes I and II of this report utilize the Log Book No. only and these should be utilized for cross-referencing.

All of the substrates coated were fabricated from Union Carbide Grade AGSR graphite. A number of these substrates utilized material which had been annealed at 5400°F for two hours.

Most of the substrates were fabricated from 24-inch-diameter billets which have a maximum grain size of 0.25 inch. This is an extruded, electrode-grade graphite with a Young's Modulus $^{\rm I}$ of 0.5 \times 10 $^{\rm G}$ psi in both the with grain and against grain directions. The CTE $^{\rm I}$ is 1.2 \times 10 $^{\rm -6/O}$ C in the with grain direction and 1.9 \times 10 $^{\rm -6/O}$ C in the against grain direction. This material, designated AGSR-VCG, was selected because its against grain CTE approaches that of PG in the "ab" plane more nearly than that of any other bulk graphite and for its low modulus of elasticity. The low CTE reduces the coating/substrate stresses induced during cooldown from deposition temperature and the reduced modulus allows the substrate to distort to further relieve these stresses. In the past AGSR-VCG has proven to be a useful substrate material for PG-coated nozzles up to 2.3-inch throat diameter.

Because of its porosity and large grain size, very coarse grained AGSR graphite has an extremely rough surface finish after machining. If a PG coating is applied to this type of surface, it tends to follow and exaggerate the roughness. Where the coating wraps around the edges of an open pore, large growth cone angles occur. The resultant large growth cones induce severe localized stresses within the coating and serve as loci for delaminations. To eliminate this problem requires the following pretreatment of the substrate surface before the PG coating is applied:

- a. Apply a coating of Union Carbide C-34 cement to the surface to be coated.
- b. Wipe off all excess coating with a dry, lint-free rag leaving cement in the pores only.
- c. Cure at 100°C for 1-2 hours.
- d. Recoat surface with a thin, uniform layer of cement.
- e. Cure at 120-130°C for 16 hours.
- f. Bake part in an inert atmosphere at 4000°F for two hours to carbonize C-34 and remove residual volatiles from graphite.
- g. Remove excess coating with medium grit emery cloth by carefully exposing substrate material without exposing new voids. No patches of cement can be present as the PG will debond from the substrate in these areas.

IAFML-TR-67-113

A few preliminary 7.0-inch deposition runs were conducted utilizing material cut from 12-inch-diameter AGSR billets and these are indicated by the designation AGSR-CG. The maximum grain size of this material is 0.06 inch. The Young's Modulus 1 is 1.2 \times 10⁶ psi in the with grain direction and 0.8 \times 10⁶ psi in the against grain direction. The CTE 1 is 1.9 \times 10^{-6/o}C in the with grain direction and 3.0 \times 10^{-6/o}C in the against grain direction. Because of its higher modulus and CTE, the finer grained AGSR-CG is inferior as a substrate material for PG. It is, however, less porous and requires no surface pretreatment before coating. Therefore, it makes an ideal, low-cost substrate material for preliminary test deposition runs.

To permit removal of the coated substrate from the deposition assembly after coating, release grooves were machined into the fixtures where they mated with the substrate. These grooves were 0.050/0.070-inch wide and from 0.100/0.300 inch in radial depth. In most cases, the coating did not bridge the release gap and the substrate was easily removed from the assembly. In cases where the coating did bridge the gap, coating delaminations occurred because of the CTE mismatch between the HLM fixture and the adjacent AGSR substrate. This was easily remedied by increasing the groove width.

The coated substrates were prepared for inspection by facing 90 mils of material from each end on a lathe using conventional techniques. The exposed coating ends were polished, successively, with 240, 320, 400 and finally 600 grit emery cloth. The coating ends were then micropolished with a water suspension of 1-micron aluminum oxide polishing compound. Microscopic examination of the polished coating ends was conducted with a Zeiss Binocular Microscope at a magnification of 120-600X. Parts were rejected, for firing, if they contained circumferential delaminations more than 3-5 growth cones in length. The coating surface was inspected visually using the alcohol wipe technique to locate exposed surface cracks. The surface was also examined for nodules. Any nodules more than 1/8 inch in diameter or raised more than 1/16 inch above the coating surface were cause for rejection, if the part was being considered for test firing.

United Technology Corporation, under subcontract to Atlantic Research, investigated advanced techniques for nondestructive testing of both coated and uncoated substrates. The principal advanced techniques studied were acoustic emission and spectral audiosonic prints. In addition, UTC utilized ultrasonics, X-ray, and alcohol wipe techniques in pursuit of NDT studies. The results of this investigation are documented in Volume II.

¹AFML-TR-67-113

SECTION VI

COATING DEVELOPMENT

1. 7.0-INCH NOZZLE THROAT INSFRTS

One 7.0-inch cylindrical and forty-five 7.0-inch nozzle throat insert fabrication runs were conducted. Five of these inserts were utilized for motor test firing, AFRPL firing data is presented in Volume I.

Figure 4 shows an as-deposited 7.0-inch throat insert. Typical coating microstructures, observed at the substrate ends, are shown in Figures 5, 6 and 7.

Deposition conditions are shown in Table II. Coating and substrate data are shown in Table III.

Three basic substrate configurations were utilized. The first of these was of a preliminary design and is shown in Figure 8. The second is shown in Figure 9 and is the configuration utilized for Test Firings SN-1, SN-2 and SN-3. The third configuration, shown in Figure 10, was similar to the second. The radii of curvature of the entrance and exit ends were increased, and the throat diameter was decreased to compensate for the after-coating dimensional changes which occur because of coating thickness variations and substrate dimensional changes. This third design was utilized for the throat inserts fired in SN-4 and SN-5.

Substrate dimensions were recorded before and after deposition for seven of the latter runs to determine the amount of substrate deformation caused by substrate/coating CTE mismatch. These data are summarized in Table IV. In all cases, the substrate outside diameter increased significantly after deposition. The two substrates on which the thinnest coating was applied showed the least amount of expansion, as would be expected. Length change dimensions were recorded in only three cases and no meaningful conclusions could be derived from them.

Four injector tip configurations were utilized. The first three of these are shown in Figures 11, 12 and 13. The fourth configuration was like the second except a second row of 36 holes was drilled below the first at an angle of 45 degrees to the injector axis. The particular configuration utilized for each run is marked on the injector tip in the deposition chamber geometry drawings.

Run 6000-1 was conducted utilizing a 7.0-inch I.D. X 7.45-inch-long cylindrical substrate. This run served to establish preliminary deposition gas flow rates, and to determine the impingement pattern of the injector. The deposition chamber geometry is shown in Figure 14. After deposition, the wall thickness was measured along three axial lines 120 degrees apart at 1/2-inch intervals along the length of the cylinder. The coating thickness profile was determined by averaging the three readings taken at each of the 1/2-inch stages. This profile is included in Figure 14.




Figure 4. As Deposited 7.0-inch Throat Insert No. 6300-1 (Coating surface stains are superficial).



Figure 5. Coating Microstructure of 7.0-inch Throat Insert No. 6300-39. Entrance End View, X60.



Figure 6. Coating Microstructure of 7.0-inch Throat Insert No. 6300-9 Exit End View, X60.




Figure 7. Coating Microstructure of 7.0-inch Throat Insert No. 6300-32. Entrance End View, 135X.

Table II. 7.0-Inch Nozzle Throat Insert Deposition Conditions.

Remarks	Tubular deposition run conducted to determine coating thickness profile.	Initial 7.0-inch nozzle throat insert deposition run.	Substrate moved up in chamber to increase coating thickness at entrance end.	Contoured mandrel used to increase proportional coating thickness at ends.	Deposition time reduced to reduce coating thickness. Gas flow rates increased to eliminate socting.	New injector tip utilized in attempt to eliminate growth on injector tip.	Lower gas flow rates tried to determine if they can be utilized with new injector tip design.	New, longer substrate used for first time. Mandrel design modified to obtain greater proportional coating thickness at exit end.	Injector moved 1/2 inch down in chamber to increase deposition rate at throat. Mandrel shortened 1/2 inch.	New deposition chamber design utilized to permit greater injector stand-off in attempt to improve coating thickness distribution.
Dep. Time (hr)	4.00	4.00	4.00	9.00	4.50	4.50	4.63	5.00	4.00	5.00
Deposition Temperature (°F)	4060	4200	4200	4000	4000	3950	3950	3950	3950	3950
Volume Percent CH4	5.1	5.1	5.1	5.1	4.9	4.9	5.1	5.1	5.1	5.1
СН 4 (SCFH)	15	15	15	15	18	18	15	15	15	15
Process N2 (SCFH)	256	256	256	556	320	320	256	256	256	256
Annulus N2 (SCFH)	24	24	24	24	30	30	24	24	24	24
Log Book No.	299-37	299-42	299-44	299-45	299-46	299-48	299-49	299-73	299-74	299-75
Run Ident No.	6000-1	6300-1	6300-2	6302-3	6300-4	6300-5	9-0029	6300-7	6300-8	6300-9

Table II. (continued).

Ren	٦	Annulus N2	Process N ₂	CH4	Volume	Deposition Temperature	Dep. Time	
Ident No.	Book No.	(SСFН)	(SCFH)	(SСFH)	CH4	(°F)	(hr)	Remarks
6300-10	1-600	24	256	15	5.1	3950	7.80	Injector moved 1/8 inch closer to substrate to increase deposition rate at exit end.
6300-11	009-2	24	256	15	5.1	3950	8.25	Mandrel shortened 1/2 inch and injector moved down 1/2 inch to increase deposition rate at throat and exit.
6300-12	600-3	24	256	15	5.1	3950	8.00	None
6302-13	009-4	24	256	51	5.1	3950	8.00	Injector orifices found to be partially blocked after deposition. May have contributed to roughness.
6300-14	9-600	24	256	15	5.1	3950	8.00	Injector orifices cleaned throughly before deposition.
6300-15	9-600	24	256	15	5.1	3950	5.75	None
6300-16	7-600	30	320	81	4.9	3950	5.00	Gas flow rates increased to improve coating surface condition.
6200-17	8-600	24	256	51	5.1	3950	7.00	Mandrel configuration modified in attempt to improve coating surface condition. Returned to old gas flow rates.
6300-18 (SN-1)	6-600	24	256	15	5.1	3950	5.83	None
6300-19	009-10	24	256	15	5.1	3950	6.73	Mandrel shortened 1/4 inch at tip, to increase deposition rate at downstream end of substrate.
6300-20	009-11	24	256	15	5.1	3950	6.75	Mandrel shortened additional 1/4 inch and injector lowered 1/4 inch to increase deposition rate at downstream end of substrate.
6300-21	009-13	30	320	15	4.1	3950	4.00	Returned to earlier deposition chamber configuration in attempt to achieve improved coating surface condition.

Table II. (continued).

Remarks	Reduced total gas flow rates and increased deposition temperature to determine effect on coating.	Shortened and rounded mandrel to improve gas flow characteristics and increase deposition rate at downstream end of substrate.	Lowered mandrel and increased CH ₄ concentration to increase deposition rate at downstream end of substrate.	Increased process N2 to reduce sooting in gas phase. Removed mandrel to determine effect on coating.	Reduced CH4 concentration to reduce sooting in gas phase.	Installed second row of holes in injector tip to direct gas to aft end of substrate.	Mandrel reinstalled to increase deposition rate.	Substrate lowered 1/2 inch and injector 1/4 inch to increase deposition rate at substrate ends.	Returned to deposition chamber configuration of 6300-17. Mandrel base bound to canister base causing mandrel to rotate with substrate.	Returned to deposition chamber configuration similar to 6300-9 and 6300-10. Mandrel mounted on posts to increase gas exhaust area.	Process N2 rate increased to reduce sooting in gas phase.
Dep. Time (hr)	5.00	6.00	0.00	5.50	5.50	5.00	5.83	5.50	6.50	6.50	6.00
Deposition Temperature (°F)	4100	4100	4100	4100	4100	4100	4100	4100	4100	4100	4100
Volume Percent CH4	4.2	4.2	6.0	4.1	2.8	2.8	2.8	2.8	4.1	3.6	2.5
сн ₄ (SCFH)	01	10	16	15	10	10	10	10	15	15	15
Process N2 (SCFH)	200	200	220	320	320	320	320	320	320	320	480
Annulus N2 (SCFH)	30	30	30	30	30	30	30	30	30	82	100
Log Book No.	009-14	009-15	91-600	009-17	009-18	009-19	009-20	009-21	009-22	009-23	009-24
Run Ident No.	6306-22	6300-23	6300-24	6300-25	6300-26	6300-27	6300-28	6300-29	6300-30	6300-31	6300-32

Table II. (continued).

		T -	Т		-	Ī	T	Т	Г	 	Ī	Τ	
Remarks	None	None	None	Deposition temperature reduced in belief that optical pyrometer was in error. Was later found to be untrue.	Deposition temperature increased, slowly and uniformly, to 4200°F at end of run to compensate for insulating effect of increasing coating thickness.	None	None	None	None	None	None	None	None
Dep. Time (hr)	00.9	9.00	5.00	6.25	6.00	5.60	5.30	5.30	5.10	5.10	4.70	3.43	5.27
Deposition Temperature (°F)	4100	4100	4100	4000	4100-4200	4100-4200	4100-4200	4100-4200	4100-4200	4100-4200	4109-4200	4100-4200	4100-4200
Volume Percent CH4	2.5	2.5	2.5	2.5	2.5	2.5	2.5	2.5	2.5	2.5	2.5	2.5	2.5
сн ₄ (SCFH)	15	15	15	15	15	15	15	15	15	15	15	15	15
Process N2 (SCFH)	480	480	480	480	480	480	480	480	480	480	480	480	480
Annulus N ₂ (SCFH)	100	100	100	001	100	100	100	100	100	100	100	100	100
Log Book No.	92-600	009-29	909-35	009-37	009-39	009-40	009-41	009-44	009-46	74-600	009-48	001-12	001-13
Run Ident No.	6300-33	6300-34 (SN-3)	6300-35	6300-36	6300-37	6300-38	6300-39	6300-40	6300-41	6300-42 (SN-4)	6300-43	6300-44	6300-45 (SN-5)

Table III. 7.0-Inch Nozzle Throat Insert Substrate and Coating Data.

	Appearance	Coating surface quality good	Coating quality good. One nodule 1/4 inch from entrance end. 1/6-inch dia X 1/16 inch high	Coating quality good. No microscopic examination	Entrance: Many short fine discontinuous delaminations in coating very near interface Exit: No cracks or delaminations: coating from throat to exit end rough and coarse in structure.	Entrance: Many short fine discontinuous delaminations in coating near interface Same overall appearance as 239-45. Exit: No cracks or delaminations; conting from throat to exit end rough and coarse in structure. Large clinker grew on injector tip.	Entrance: A line of discontinuous determinations visible near interface extend for 360 degrees. Exit: No flaws.	Entrance: A few very fine short (2 to 6 growth cones long) delaminations visible near interface. Exit: No. flaws. Coating surface smooth	Entrance: Coating texture is wery rough with broad growth cones. A few short delaminations, extending through 6 to 10 growth cones and one delamination approximately 1 1/2-inch long, are visible. Exit ares: No cracks or delaminations.	Coating surface texture is rough through- out. Entrance and Exit: No cracks or delaminations.	Entranca: No cracks or deteminations. Exit: Two very short fine detaminations. 10 to 20 growth cones long, near substrate interface.
ils/hr)	Exit		8.	5.	6.9	12.0	6.3	6.8	9.7	8.5	9.0
Deposition Rate (mils/hr)	Throat		10.5	16.5	15.0	0.91	16.0	7.	12.0	0.81	8.7
Depositi	Entrance		13.8	7.0	13.2	14.9	16.9	14.5	16.0	2	7.6
(ii)	Exit		0.019	0.026	0.056	0.054	0.042	0.041	0.046	0.034	0.030
Coating Thickness (in)	Throat		0.042	990.0	960.0	0.072	0.072	0.068	0.00	0.072	0.041
Coating	Entrance		0.055	0.028	0.079	0.067	0.076	0.067	0.080	0.033	0.038
Substrate	Configuration	Tubular	-	-	-	-	-	≤	8	8	~
	Material	AGSR-CG	AGSR-CG	AGSR-CG	AGSR-CG	AGSR-CG	AGSR-VCG Surface Precoated	AGSR-VCG Surface Precoated	AGSR-VCG Surface Precoated	AGSR-VCG Surface Precoated	AGSR-VCG Surface Precoated
9	Book No.	299-37	299-42	299-44	299-45	299-46	299-48	299-49	299-73	299-74	299-75
Ren	Ident. No.	6000-1	6300-1	6300-2	6302-3	23004	6300-5	6300-6	6300-7	6300-8	6300-9

Table III. (continued).


	Appearance	Entrance: Delaminated in three places near coating surface. Two are 20 degrees long and the third 5 degrees long and the third 5 degrees long and the third 5 degrees long these delaminations. Exit: Delaminated for 360 degrees near the substrate interface.	Entrance: Fine discontinuous delamination begins at the UTC 45-degrees mark and extends around to within 45 degrees of the UTC zero degree mark. Exit: At 70-degrees point a fine discontinuous delamination begins and extends for 90 degrees. Remainder of coating is good.	Coating rough and irregular.	Coating rough and irregular. Entrance end: Three minute delaminations, 8 to 10 growth cones in length. Exit end: Several short fine delaminations near substrate interface.	Coating surface still somewhat rough. Three small growths visible in throat area seem to originate near coating surface. No cracks or delaminations visible at either and.	Coating surface fair. Slightly better than previous run.	Coating surface fair.	Coating surface is rough in texture from entrance end to throat. Coating at entrance and contains an occasional delamination, 3 to 5 cones long near interface. Coating at exit end contains a series of short, fine discontinuous delaminations near middle of coating thickness.	No cracks or delaminations. Surface texture coarse from entrance end to throat.
ils/hr)	Exit	93	3	3	3	3	5.9	7.6	2.7	5.7
Deposition Rate (mils/hr)	Throat	3	2	9:	10.8	9.	6.7	10.8	10.1	6.0
Depositi	Entrance	*2	69	5.5	69	3	6.4	6.2	10.1	10.1
(in)	Exit	0.044	0.052	0.049	0.051	0.051	0.034	0.038	0.050	0.033
Coating Thickness (in)	Throat	0.054	0.068	0.093	0.086	0.077	0.050	2.054	0.071	0.052
Coating	Entrance	0.058	0.057	0.044	0.055	0.050	0.037	0.031	0.071	0.059
Substrate	Configuration	₹	28	28	28	28	i	20	20	2C
Subs	Material	AGSR-VCG Surface Precoated	AGSR-VCG Surface Precoated	AGSR-VCG Surface Precoated	AGSR-VCG Surface Precoated	AGSR-VCG Surface Precoated	Recoated 6300-12	AGSR-VCG Surface Precoated	AGSR-VCG Surface Precoated	AGSR-VCG Surface Precoated
1	Book No.	1.600	2-600	009-3	4-600	9-600	9-600	2-600	8-600	6-600
	Ident. No.	6300-10	6300-11	6300-12	6302-13	6300-14	6300-15	6300-16	6300-17	6300-18 (SN-1)

Table III. (continued).

	Appearance	No cracks or delaminations. Surface texture coarse from entrance end to throat	Entrance end: No cracks or delaminations. Surface texture is rough. Exit end: Two mils of surface coating spalled; remaining coating shows no flaws.	Coating from entrance end to throat rough.	Coating from entrance and to throat rough.	Coating quality at entrance end improved. However, it is still somewhat rough.	Mandrel and entrance end of nozzle covered with sooty growths. Exit end of costling irregular and also contains several sooty growths.	Substrate completely covered with clinker-like deposits.	No coating from throat to exit end.	Costing fairly clean. A few large nodules (1/16-inch diameter) at entrance end.	Coating of fair quality. A few large nodules at entrance end.	Coating rough with several large rodules at entrance end.	Costing very rough and irregular. No meaningful measurements could be taken.	Coating from entrance end to throat contains many flower-like carbon growths.	Coating and substrate cracked radially in two places during machining. Coating surface much smoother than in previous runs.	No cracks or delaminations. Coating quality appears to be good.
ils/hr)	Exit	2	9.6	9.0	9.0	5.2	1	Ĺ	ı	2	8.8	8.2	1	3		7.5
Deposition Rate (mils/hr)	Throat	2	2	113	7.6	3	2	1	ı	**	8		1	2	10.0	10.0
Deposition	Entrance	9.2	6.6	17.5	12.2	0.11	1	1	10.4	\$	8.0	7.3	ı	0.0	7.6	8.7
(ii)	Exit	0.041	0.038	0.036	0.033	0.031	t	l	I į	0.017	0.034	0.034	ı	9.0	0.048	0.045
Coating Thickness (in)	Throat	0.055	0.059	0.045	0.038	0.041	0.043	ı	1	0.037	0.048	0.048	ı	0.058	0.060	0.060
Coating	Entrance	0.062	0.067	0.00	0.061	990.0	ı	i	0.057	0.023	0.029	0.040	1	0.052	0.058	0.052
Substrate	Configuration	20	5 C	5 C	ı	I	I	1	2	•	1 5	22	22	SC.	5 C	5 0
	Material	AGSR-VCG Annealed. Surface Precoated	AGSR-VCG Annealed. Surface Precoated	AGSR-VCG Surface Precoated	Recosted 6300-21	Recosted 6300-21	Recoated 6300-21	Recosted 6300-21	AGSR-VCG	-	Recosted 6300-26	AGSR-VCG Surface Precoated	AGSR-VCG Surface Precoated	AGSR-VCG Surface Precoated	AGSR-VCG Surface Precoated	AGSR-VCG Annealed Surface Precoated
3	Book No.	009-10	11-600	009-13	11-600	009-15	91-600	009-17	81-600	61-600	008-20	009-21	009-22	009-23	009-24	009-26
Res	Ident. No.	6300-19 (SN-2)	6300-20	6300-21	6300-22	6300-23	6300-24	6300-25	6300-26	6300-27	6300-28	6300-29	6300-30	6300-31	6300-32	6300-33

Table III. (continued).

Run	Log		Substrate	Coating	Coating Thickness (in)	(in)	Deposition	Deposition Rate (mils/hr)	ils/hr)	
Ident. No.	Book No.	Material	Configuration	Entrance	Throat	Exit	Entrance	Throat	Exit	Appearance
6300-34 (SN-3)	009-29	AGSR-VCG Annealed. Surface Precoated	22	0.052	0.055	0.040	8.7	9.5	6.7	No cracks or delaminations.
6300-35	009-35	AGSR-VCG Annealed. Surface Precoated	2C	0.042	0.047	0.034	4.8	4.6	9	No apparent defects. Sent to TRW. Thin delaminations observed leter.
6300-36	009-37	AGSR-VCG Annealed. Surface Precoated	2C	0.056	0.068	0.049	0.6	10.9	7.8	Coating somewhat rough and grayish in color. No significant delaminations visible.
6300-37	009-39	AGSR-VCG Annesled. Surface Precoated	2C	0.048	0.056	0.043	0.0	9.3	7.2	No examination of coating ends. Substrate and coating cracked axially Coating surface quality is ecod.
6300-38	009-40	AGSR-VCG Annealed. Surface Precoated	2C	0.050	0.054	0.045	6. 6.	9.6	6	No defects as deposited, 90-degrees delamination observed subsequently.
6300-39	009-41	AGSR-VCG Annealed. Surface Precoated	22	0.054	0.055	0.043	10.2	10.4	<u>.</u>	No defects.
6300-40	909-44	AGSR-VCG Annealed.	20	0.047	0.057	0.044	6 .9	10.8	8.3	Entrance end stuck to coating fixture and delaminated when separated
6300-41	97-600	AGSR-VCG Annealed. Surface Precoated	2D	0.048	0.056	0.042	9.4	6.01	8.2	Coating and substrate split axially in two places 90-degrees apart.
63-0042 (SN-4)	009-47	AGSR-VCG Annealed. Surface Precoated	м	0.051	0.057	0.043	10.0	11.2	*	No significant flaws.
6300-43	009-48	AGSR-VCG Annealed. Surface Precoated	ო	0.048	0.046	0.036	10.2	8.6	1.7	No significant flaws.
6300-44	002-12	AGSR-VCG Annealed. Surface Precoated	м	0.036	0.038	0.029	10.5	Ξ	8	Entrance end: No cracks or delamination Exit end: Occasional short, very fine delaminations visible, in coating, near proces in subdesses
6300-45 (SN-5)	001-13	AGSR-VCG Annealed. Surface Precoated	m	0.054	0.057	0.047	10.2	10.8	80	Entrance end: No cracks or delamination Exit end: No cracks or delaminations.






Figure 8. 7.0-inch Nozzle Throat Insert Substrate Configurations 1 and 1A.




Figure 9. 7.0-inch Nozzle Throat Insert Substrate Configuration 2 (Including groove modifications).





Figure 10. 7.0-inch Nozzle Throat Insert Substrate Configuration 3.

Table IV. 7.0-Inch Nozzle Throat Insert Substrate Dimensional Changes After Coating.

Percent Change in Substrate Dimensions After Coating

				D	13 7116	Coating
Run Ident No.	Log Book No.	Substrate Material	Entrance OD	Throat OD	Exit OD	Length
6300-38	009-40	AGSR-VCG (Annealed)	0.36	0.20	0.24	-0.03
6300-39	009-41		0.40	0.16	0.21	0.03
6300-40	009-44		0.15	0.12	0.16	_
6300-42 (SN-4)	009-47		0.46	0.23	0.25	-
6300-43	009-48		0.41	0.26	0.26	_
6300-44	001-12		0.22	0.17	0.18	-0.9
6300-45 (SN-5)	001-13	↓	0.38	0.34	0.34	_






Figure 11. 7.0-inch Injector Tip Configuration 1.




Figure 12. 7.0-inch Injector Tip Configuration 2.




Figure 13. 7.0-inch Injector Tip Configuration 3.




Figure 14. Deposition Chamber Geometry of Run No. 6000-1.

Run 6300-1, the first 7.0-inch nozzle throat insert deposition run, was conducted utilizing the deposition chamber geometry shown in Figure 15. The deposition gas flow rates were the same as those of the previous run. Post-deposition examination showed the coating surface finish to be acceptable with the exception of one small nodule near the entrance end. No cracks or delaminations were visible in either the coating or the substrate. The high deposition rate at the entrance end indicated that the substrate was positioned too low in the deposition chamber.

Run 6300-2 was conducted using the same procedure and gas flow rates as the previous deposition run. The mandrel was cleaned to the original diameter of 5.08 inches and positioned in the center of the nozzle I.D. as before to reduce the cross-sectional area within the deposition chamber. The deposition chamber geometry (Figure 16) was similar to that of the previous run. The substrate was moved up one inch to increase the deposition rate in the throat and downstream areas. Post-deposition examination showed the coating surface to be similar to that of the previous run. The deposition rate decreased by 49 percent at the entrance end, increased by 57 percent at the throat, and increased by 35 percent at the exit end. Because of the minimal thickness of the coating at the ends, no microscopic examination was conducted.

Run 6302-3 was conducted using the same gas flow rates as the previous run. To increase the deposition rate at the entrance end, relative to the throat, the substrate was moved down 1/2 inch in the deposition chamber. This substrate position was midway between that of 6300-1 and 6300-2. An attempt was made to increase the deposition rate at the exit end by tapering the mandrel diameter out from the throat area toward the exit end of the substrate. This resulted in a decrease of 52 percent in the annular cross-sectional area at the exit end. The deposition chamber geometry is shown in Figure 17. Post-deposition examination showed the coating surface to be rough from the throat area to the exit end indicating soot formation within the gas stream in this area. Evidence of this sooting could be seen on the mandrel where a V-shaped, clinkerlike deposit had formed. The coated substrate was trimmed polished and examined microscopically at both ends. The coating contained many short, fine delaminations at the entrance end. No flaws were visible at the exit end. The deposition rate increased by 89 percent at the entrance end, decreased by 9 percent at the throat, and increased by 43 percent at the exit end.

Run 6300-4 was conducted using the same deposition chamber geometry (Figure 17) as the previous run. The process and annulus nitrogen flow rates were increased by 25 percent and the methane rate was increased by 20 percent. This effectively reduced the methane concentration by 4 percent. The increase in nitrogen rates and reduction of methane concentration were an attempt to reduce the amount of sooting in the gas phase and thereby improve the coating surface texture. Post-deposition examination showed the coating to be rough from the throat to the exit end, as in the previous run. A clinkerlike deposit had grown on the mandrel in the same manner as before. This problem was found to be related to misalignment of the injector gas exit ports. Although the increase in gas flow rates did not solve the coating roughness problem, it did increase the overall deposition rate and improve the uniformity of the axial coating thickness profile. The deposition rate increased by 13 percent at the entrance end, 7 percent at the throat, and 29 percent at the exit end.




Figure 15. Deposition Chamber Geometry of Run No. 6300-1.




Figure 16. Deposition Chamber Geometry of Run No 6300-2.




Figure 17. Deposition Chamber Geometry of Run No's 6302-3 and 6300-4.

Run 6300-5 was conducted using the same deposition gas flow rates as the previous run. A new injector tip (Configuration 2) was utilized to correct the coating roughness problem encountered in the previous runs. The deposition chamber geometry was similar to that of the previous run and is shown in Figure 18. Post-deposition examination showed the coating to be smooth and free of surface defects. No evidence of sooting could be seen on either the substrate or the mandrel. Microscopic examination of the polished coating ends revealed delaminations within the coating at the entrance end. These delaminations were the result of high stress levels at the coating end and were, in this case, directly related to the greater coating thickness of the entrance end. The increased deposition rate at the entrance end appears to be related to the impingement pattern of the gas cone on the substrate with the new injector tip configuration. As can be seen in Figure 18, the gas cone strikes the substrate approximately 1/4 inch higher than in the previous run. Because of this, the deposition rate increased by 13 percent at the entrance end and decreased by 22 percent at the exit end. The rate at the throat did not change.

Run 6300-6 was conducted utilizing the gas flow rates of the first four 7.0-inch runs to determine if the new injector tip design would function properly at the reduced rates. This run would, therefore, be comparable to Run 6302-3. The deposition chamber geometry was the same as that of the previous run (Figure 18). Post-deposition examination of the polished coating ends revealed a few very short, fine delaminations at the entrance end. These were minor in nature, and none were more than a few growth cones in length. Stress relief grooves were machined into the ends of this substrate before deposition. This represented the first use of these grooves in the large nozzle sizes, and it appears that they are effective in reducing coating end stresses as has been demonstrated in the past with smaller nozzle shapes. The reduction in gas flow rates yielded the expected reduction in deposition rate. Compared to 6302-3, the coating deposition rate at the entrance end increased somewhat and that at the exit decreased slightly. The rate at the throat showed very little change. These effects were consistent with the gas impingement pattern of the new injector tip on the forward end of the substrate.

Run 6300-7 was the first conducted using substrate Configuration 2. The deposition chamber geometry, shown in Figure 19, was modified to accommodate the longer substrate, but was in general similar to that of 6300-6. Deposition gas flow rates were the same as those of 6300-6. Post-deposition examination showed the coating to be disproportionately thick at the entrance end. The throat thickness was satisfactory, and the exit thickness was acceptable, although it was somewhat thinner than desired. The coating texture was rough throughout, especially at the entrance end. Microscopic examination disclosed no serious cracks or delaminations in either coating or substrate.

Run 6300-8 was conducted with the injector 1/2 inch lower in the deposition chamber. The mandrel was shortened by 1/2 inch at the tip with an appropriate change in angle. The deposition chamber geometry is shown in Figure 20. These changes were made to increase the proportional deposition rate from the throat to the exit end. Deposition gas flow rates were the same as those of the previous run. Post-deposition examination showed the deposition rate at the throat to be more than twice that at either end. This resulted in an unacceptable coating thickness profile. The coating surface texture was also rough as in the previous run.




Figure 18. Deposition Chamber Geometry of Run No's 6300-5 and 6300-6.




Figure 19. Deposition Chamber Geometry of Run No. 6300-7.




Figure 20. Deposition Chamber Geometry of Run No. 6300-8.

Run 6300-9 was conducted utilizing a modified deposition chamber geometry, as shown in Figure 21. This geometry permitted a greater injector standoff distance so the deposition gas cone could expand and cover the substrate surface. A new injector tip (Configuration 3) was utilized to accommodate this increased standoff. Deposition gas flow rates were the same as those of the previous run. Post-deposition examination showed the overall coating thickness to be less than acceptable for firing. The coating quality and thickness distribution were superior to that achieved using the old injector design. No cracks or delaminations were present in the coating at the entrance end. The coating at the exit end exhibited two very fine delaminations ten to twenty growth cones in length. These were relatively insignificant and the coating would have been considered acceptable for motor firing were it thick enough.

Run 6300-10 was conducted utilizing the same deposition chamber geometry (Figure 21) and gas flow rates as the previous run. The deposition time was increased to obtain an average coating thickness of 60 mils in the forward section of the substrate. The injector was moved down 1/8 inch to increase the proportional deposition rate at the exit end. Post-deposition examination showed the coating to have bridged the release gap between the entrance approach section and the entrance end of the substrate, bonding the two parts together. The entrance section was CS graphite and of higher thermal expansion than AGSR. This induced excessive stresses in the coating on the entrance piece and it delaminated. Because the coating had bridged the two parts, the delamination propagated into the coating on the substrate. The removal of an additional 0.250 inch of material from the nozzle entrance end was required to remove the effects of this delamination. The coating at the exit end also contained a delamination near the substrate interface extending for 360 degrees. There was no bridging of the coating indicating that this delamination was the result of excessive residual stress at the exit end. The deposition rate was highest at the entrance end of the substrate and decreased toward the downstream end.

Runs 6300-11 through 6300-15 were all conducted using the deposition chamber geometry shown in Figure 22. The deposition gas flow rates were the same as those of the previous run. Post-deposition examination of the five parts showed the coatings to be so rough in surface texture as to be unacceptable.

Run 6300-16 was conducted utilizing the depositon chamber configuration of the previous five runs (Figure 22). The annulus and process nitrogen rates were increased by 25 percent and the methane rate was increased by 20 percent in an attempt to reduce sooting in the gas phase and improve the coating surface texture. Post-deposition examination showed some improvement in the coating surface texture. The deposition rate at the entrance end was too low and, therefore, the coating was disproportionately thin in this area.

Runs 6300-17 through 6300-19 were all conducted using the deposition chamber geometry shown in Figure 23. Deposition gas flow rates were the same as those of the runs just prior to 6300-16. The coating achieved in 6300-17 contained a series of short, fine delaminations at the exit end. The coating from 6300-18 was somewhat thinner, and contained no cracks or delaminations. This part was selected for use in the first 7.0-inch test firing of the program, SN-1. The third part, 6300-19, was similar to 6300-18 and was selected for Test Firing SN-2. The coatings on both of these parts were somewhat rough from the entrance end to the throat plane and were not of the quality achieved later in the program. This probably accounts for their exceptionally poor performance during firing. See Volume I.




Figure 21. Deposition Chamber Geometry of Run No's 6300-9 and 6300-10.




Figure 22. Deposition Chamber Geometry of Run No's. 6390-11 thru 6300-16.




Figure 23. Deposition Chamber Geometry of Run No's. 6300-17 thru 6300-19 and Run No. 6300-30.

Run 6300-20 was conducted using the deposition chamber geometry shown in Figure 24. The injector was moved 1/4 inch closer to the substrate than in the previous run, and the mandrel was shortened by 1/2 inch in an attempt to increase the deposition rate at the exit end. All other conditions were the same as those of Run 6300-19. Post-deposition examination showed the injector movement to have had little effect on the coating thickness profile. The coating surface from the entrance end to the throat was rough, as in the previous runs. At the exit end, a 2-mil-thick layer of the coating surface separated after the trimming operation. A buildup of soot and clinkers formed on one area of the mandrel. As the substrate rotated past this area, a change in the deposition flow pattern resulted that was reflected as a spiraling band within the coating. This band represented an area of extensive sooting within the coating and was probably related to the spallation at the coating surface. The polished coating ends showed no cracks or delaminations.

Runs 6300-21 through 6300-24 represented a return to a geometry similar to that utilized for the first eight 7.0-inch nozzle insert deposition runs. The gas exhaust area was increased by setting the mandrel body on four 1/2-inch-diameter posts to prevent clogging. The deposition chamber geometries for these four runs are shown in Figures 25 through 28. None of the coatings fabricated during these four runs were acceptable.

Runs 6300-25 and 6300-26 were conducted with the mandrel removed and at an increased process nitrogen flow rate in an attempt to eliminate the sooting problem encountered in the previous four runs. The deposition chamber geometries are shown in Figures 29 and 30. Neither of these runs produced an acceptable coating.

Run 6300-27 was conducted in a manner similar to the previous run. The deposition chamber geometry is shown in Figure 31. The Configuration 2 injector tip was modified to Configuration 4 by drilling a second series of orifices below the first at a 45-degree angle. This angle of inclination is such that when the axis of the first series of orifices intersects the substrate above the throat line, the axis of the second series intersects the substrate between the throat and the exit end. Post-deposition examination showed the coating surface texture to be improved over that of the previous several runs. The deposition rate at the ends was too low in comparison with that of the throat.

Run 6300-28 was conducted with the mandrel reinstalled and utilized the modified injector tip. The deposition chamber geometry is shown in Figure 32. Post-deposition examination showed the coating surface texture to be of fair quality. The disparity between the end coating thicknesses and the throat showed little improvement over that of the previous run.

Run 6300-29 was conducted in the same manner as the previous run with the substrate positioned 1/2 inch lower in the deposition chamber to increase the deposition rate at the entrance end. The deposition chamber geometry is shown in Figure 33. Post-deposition examination showed the changes in deposition chamber geometry to have had the desired effect on the coating deposition rate profile. However, the coating was rough in texture and contained several large nodules at the exit end.




Figure 24. Deposition Chamber Geometry of Run No. 6300-20.




Figure 25. Deposition Chamber Geometry of Run No. 6300-21.




Figure 26. Deposition Chamber Geometry of Run No. 6300-22.




Figure 27. Deposition Chamber Geometry of Run No. 6300-23.




Figure 28. Deposition Chamber Geometry of Run No. 6300-24.




Figure 29. Deposition Chamber Geometry of Run No. 6300-25.




Figure 31. Deposition Chamber Geometry of Run No. 6300-27.




Figure 32. Deposition Chamber Geometry of Run No. 6300-28.




Figure 33. Deposition Chamber Geometry of Run No. 6300-29.

At this time, the short deposition chamber geometry was abandoned permanently.

Run 6300-30 was conducted utilizing the same deposition chamber geometry as 6300-17 (Figure 23), including the injector tip. The high nitrogen flow rates were maintained to help eliminate sooting in the gas phase. The methane rate was increased to increase the deposition rate. Post-deposition examination showed three of the six mandrel exhaust ports to be completely clogged by hard, sooty deposits, and the other three were almost clogged. The mandrel, which is supposed to remain stationary, had rotated with the nozzle substrate and was covered with hard, sooty deposits. The corresponding nozzle area was covered by a thick, rough PG deposit.

Run 6300-31 was conducted utilizing the deposition chamber geometry shown in Figure 34. The mandrel body was mounted on six 1/2-inch-diameter posts to increase the gas exhaust area and eliminate clogging. The mandrel was also pinned to the furnace base so it could not rotate. Post-deposition examination showed the coating to be covered with flowerlike carbon deposits in the entrance area. A continuous midplane delamination was visible within the coating which resulted from a brief interruption in gas flow during deposition. The mandrel gas exhaust area remained virtually unrestricted. The deposition rate profile was acceptable.

Runs 6300-32 through 6300-45 were all conducted using the deposition chamber geometry shown in Figure 35. At this time, the final deposition gas flow rates were established and were unchanged throughout the remaining 7.0-inch nozzle throat insert fabrication runs. At Run 6300-37, the deposition temperature was increased 100°F during deposition to compensate for the insulating effect of the increasing coating thickness (see Section V). All of the coatings fabricated during this series were smooth in surface texture with the exception of 6300-36, which was deposited at a deposition temperature of 4000°F. This indicates that a deposition surface temperature of 3800°F is minimal, and for this reason an indicated canister backside temperature of 4100-4200°F was utilized for the remaining nine runs. Examination of the polished coating ends showed a fine, continuously renucleated microstructure. Occasional intraconical delaminations were present in areas adjacent to large pores in the substrate. Two of the inserts cracked axially after deposition, indicating that even unbroken parts contained stresses approaching that of failure. Three of the nozzle throat inserts produced, 6300-34, 6300-42 and 6300-45, were utilized for Test Firings SN-3, SN-4 and SN-5, respectively.

2. 10.6-INCH NOZZLE THROAT INSERTS

Three 10.6-inch throat diameter nozzle insert deposition runs were conducted.

Deposition conditions are shown in Table V. Coating and substrate data are shown in Table VI.

The same injector tip design was utilized for all three runs and was the same as that used during the initial 7.0-inch deposition runs. (See Figure 11.)

One substrate design was used and this is shown in Figure 36.




Figure 34. Deposition Chamber Geometry of Run No. 6300-31.




Figure 35. Deposition Chamber Geometry of Run No's. 6300-32 thru 6300-45.

Table V. 10.6-inch Nozzle Throat Insert Deposition Conditions.

	-	Γ	_		ě	
	Kemarks	- Nove		Nitrogen rates increased and CH4 concentration	decreased to reduce sootir	Rotator failed during deposition.
Dep.		5.00		5.00		5.00
Dep.		3950		3950		3950
Volume Percent CHA		5.1		4.5		4.5
CH4 (SCFH)		18		24		24
Process N2 (SCFH)		320		448		448
Annulus N2 (SCFH)	1	30		80		80
Log Book No.	200 63	76-667		299-53		299-56
Run Ident No.	7300.1	-000		7300-2		7300-3

Table VI. 10.6-inch Nozzle Throat Insert Substrate and Coating Data.

0	I as Bank	Substrate	rate	Coating	Coating Thickness (in)		Deposition Rate (mils/hr)	Rate (mi	(Jul)	
Ident. No.		Material	Configuration	Entrance Throat Exit	Throat	Exit	Entrance Throat Exit	Throat	Exit	Appearance
7300-1	299-52	AGSR-VCG (surface treated)	-	0.040	0.039	0.008	8.0	8.7	1.6	1.6 Coating from entrance end to throat contains several flower-like carbon growths. No microscopic examination.
7300-2	299-53	Reused above part	-	0.012	0.351	0.024 2.4	5.4	10.2	\$	Coating surface clean and smooth. A narrow annular ring of carbon growths grew at entrance end. No microscopic examination.
7300-3	299-56	AGSR-VCG (surface treated)	-	0.040	0.054	0.027 (Avg.)	8	8.01 8	**	Surface condition good. No cracks or delaminations visible at coating ends. Coating thickness varies from 0.015 to 0.039 at exit end.




Figure 36. 10.6-inch Nozzle Throat Insert Substrate Configuration.

Run 7300-1, the first of the 10.6-inch series, was conducted utilizing the deposition-chamber geometry shown in Figure 37. Deposition conditions were selected from contemporary 7.0-inch deposition runs. Post-deposition examination showed considerable amounts of soot and flowerlike carbon growths to have accumulated on the inner surface of the deposition chamber. The coating surface was sprinkled with flowerlike carbon growths. Except for these growths, the coating was of acceptable quality.

Run 7300-2 was conducted at a nitrogen flow rate 59 percent higher than that of the previous run. The methane rate was increased by only 33 percent which decreased the concentration by 12 percent. These changes were made to reduce the amount of sooting in the gas phase and, therefore, eliminate the deposits of soot and flowerlike carbon growths which occurred in the previous run. The substrate was moved up 0.6 inch in the deposition chamber and the injector was moved down 0.25 inch to increase the deposition rate at the exit end. The deposition chamber geometry is shown in Figure 38. Post-deposition examination showed the coating surface quality to be good. The only defect was a narrow annular ring of carbon growths which had accumulated at the entrance end. This ring shadowed the coating surface and caused a substantial reduction in the coating thickness at the entrance end.

Run 7300-3 was the last 10.6-inch deposition run conducted and utilized the deposition chamber geometry shown in Figure 39. A new, larger diameter mandrel was used to increase the coating deposition rate. Deposition process conditions were the same as those of the previous run. The deposition chamber rotator mechanism failed during deposition and, consequently, no rotation occurred throughout the latter half of the cycle. Post-deposition examination showed no flaws in the coating surface or the polished coating ends. There was no evidence of the annular ring of growths which had formed in the previous run. The lack of rotation resulted in an unequal coating thickness at the exit end. This part split axially during shipment to the Atlantic Research Pine Ridge Facility about two weeks after deposition. The exact cause of this failure is unknown, but it is quite likely that the part was mishandled during shipment.

3. 13.0-INCH NOZZLE THROAT INSERTS

Iwelve 13.0-inch-throat diameter nozzle insert fabrication runs were conducted.

Deposition conditions are shown in Table VII. Coating and substrate data are shown in Table VIII.

The injector tip configuration utilized for these runs was the same as that used in several of the 7.0-inch deposition runs. (See Figure 12.)

All substrates were of the configuration shown in Figure 40.

Run 8300-1, the first of the 13.0-inch series, was conducted utilizing gas flow rates established during the 10.6-inch series. The deposition chamber geometry is shown in Figure 41. After deposition, the area around the injector tip was filled with clinkerlike deposits. The nozzle substrate coating contained scattered flowerlike carbon growths from the entrance end to the throat. The area from the substrate throat to the gas exhaust ports was clogged with soot and clinkerlike deposits. The coating was cleaned and measured, but no microscopic examination was conducted.




Figure 37. Deposition Chamber Geometry of Run No. 7300-1.




Figure 38. Deposition Chamber Geometry of Run No. 7300-2.




Figure 39. Deposition Chamber Geometry of Run No. 7300-3.

Table VII. 13.0-inch Nozzle Throat Insert Deposition Conditions.

Remarks	Pilot 13 in. deposition. Injector rests on tip of mandrel	N ₂ rate increased to reduce sooting within gas stream.	CH4 concentration increased to increase deposition rate	Total gas flow rate increased to reduce sooting within gas stream	Mandrel size reduced to prevent clogging of annular gas exhaust area	Mandrel size increased to increase deposition rate	Process N ₂ rate increased to reduce sooting within gas stream. At 2.83 hours gas exhaust tube collapsed causing a temporary increase in furnance gas pressure.	Repeat of above run with repaired gas exhaust tube.	Contoured entrance section utilized in deposition chamber to reduce turbulance and, thereby, eliminate sooting.	Mandrel removed to determine its affect on sooting in deposition chamber.	Injector lowered to increase deposition rate at downstream end of substrate. Gas exhaust tube plugged near end of run.	Gas exhaust tube removed to increase exhaust area. Hot gas leaked through brickwork and forced early termination of run.
Dep. Time (hr)	4.00	2.00	5.57	2.00	4.00	4.00	4.75	8.00	4.83	6.33	1.00	6.00
Dep. Temp. (°F)	3950	3950	3950	3950	. 3950	3950	3950	3950	3950	3950	3950	3950
Volume Percent CH4	4.5	3.8	4.4	4.5	4.5	4.5	3.9	3.9	3.9	3.9	9.6	3.9
CH4 (SCFH)	24	24	28	35	35	35	32	32	32	32	32	32
Process N2 (SCFH)	448	538	538	673	673	673	740	740	740	740	740	740
Annulus N2 (SCFH)	80	96	96	88	88	88	75	75	75	75	75	75
Log Book No.	299-60	299-61	29-65	299-63	299-64	299-65	299-66	29-667	299-69	299-70	299-71	299-72
Run Ident No.	8300-1	8300-2	8300-3	8300-4	8300-5	8300-6	8300-7	8300-8	8300-9	8300-10	8300-11	8300-12

Table VIII. 13.0-inch Nozzle Throat Insert Substrate and Coating Data.

	Appearance	Injecter area covered with clinkers. Entrance end to throat line sprinkled with hard flower-like carbon growths. Exit end coated with soft carbon deposits. Annuler area at exit end filled with clinkers.	Similar to above. Entrance and to throat is clean. Exit and covered with soft carbon deposits.	Entrance area to throat line sprinkled with hard flower-like carbon growths. Ext end cleaner than first two deposition runs but still has many sooty areas.	Entrance end to throat line covered with flower-like carbon growths. Exit end coated with soft carbon deposit.	Entrance end to throat line covered with flower-like carbon growths. Exit end good.	Entrance end to throat line covered with flower-like carbon growths. Exit end good.	Entrance end clean except for forward edge which contains a thin annular ring of hard deposits. Exit end good.	Coating from entrance and to throat contains several hard, flower-like carbon growths. Exit and clean except for extreme edge.	Coating from entrance and to throat contains several hard, flower-like carbon growths. Exit and clean except for extreme edge.	Coating is clean except for entrance and exit ends around which a 0.1 to 0.2-in wide annular ring of growths accumulated.	Entrance area: Coating tapers rapidly toward edge in a band 1/4 inch wide and textending for 360 degrees around perimeter. One flower-like carbon growth, 5/8-inch long X 1/2 inch wide X 1/4 inch high. halfway between end and throat. Exit Area: Coating tapers rapidly toward edge, in a band 1/2 inch wide and extending for 360 degrees around perimeter.	Similar to above with many, small, newly formed carbon flowers throughout coating surface.
ls/hr)	Exit	2	ı	9.	1	3	63	7	ı	7	Ξ	0.5	1
Deposition Rate (mils/hr)	Throat	5.9	2.2	7.2	10.2	6.5	E. 6	7.2	7.9	£.	1.3	2.9	4.2
Depositio	Entrance	3.5	1	1	ı	1	1	1	1	ı	3.2	2	l
(ii)		0.013	<0.001	0.031	<0.001	0.025	0.025	0.020	NE	0.010	0.007	0.002	NE.
Coating Thickness (in)	Throat Exit	0.026	0.26	0.040	0.51	920.0	0.037	0.034	0.063	0.045	0.032	890'0	0.025
Coating	Entrance	0.014	<0.001	<0.001	<0.001	NE.	NE.	NE.	NE.	<0.001	0.020	0.035	NE NE
ate	Configuration		-	-		_	-	-	-	-	-	-	par
Substrate	Material	AGSR-VCG (surfaced treated)	Reused above part	Reused above part	Reused above part	Reused above part	Reused above part	Reused above part	Reused above part	Reused above part	Reused above part	AGSR-VCG (surface treated)	AGSR-VCG (surface treated)
Los Book	No.	299-60	19-662	29-662	299-63	299.64	299-62	299-662	299-67	299-69	299-70	299-71	299-72
Run	ide t No.	83 J.I	83 0-2	83 7-3	83 74		82 3-6	83 27	83 7 6	83 3-9	83)3-10	8309-11	8300-12




Figure 40. 13.0-inch Nozzle Throat Insert Substrate Configuration 1.




Figure 41. Deposition Chamber Geometry of Run No. 8309-1.

Run 8300-2 was conducted with a 20 percent increase in nitrogen flow rate. The methane flow rate was not changed. Two minor changes were made in the deposition chamber geometry (Figure 42). The mandrel was shortened by 1/4 inch at the tip and rounded. The lower mandrel radius was increased to facilitate gas flow through the throat and into the exhaust ports. After deposition, the gas inlet area was somewhat cleaner than the previous run. There were still, however, considerable amounts of sooty deposits in this area. The coated surface of the nozzle substrate was clean from the entrance end to the throat. The area from the substrate throat to the exit end was covered with hard, sooty deposits. Similar deposits had completely filled and blocked the gas exhaust section. The coating ends were too thin to be measured, so only the throat thickness was recorded. The deposition rate at the throat decreased by 20 percent, which corresponds closely with the 16 percent reduction in the methane concentration of the deposition gas.

Run 8300-3 was conducted using the same nitrogen flow rates as the previous run. The methane flow rate was increased by 17 percent to boost the depositon rate. The mandrel was shortened by 1/2 inch and the injector lowered 1/2 inch. The major diameter of the mandrel was tapered to increase the annular gas exhaust area in the lower area of the chamber. The deposition chamber geometry is shown in Figure 43. After 5 hours and 34 minutes of deposition, the exhaust area of the deposition chamber plugged, and the run was terminated. Post-deposition examination revealed the same type of sooty deposits in the gas inlet and exhaust areas as before. The nozzle coating showed scattered flowerlike carbon growths like those of the first 13.0-inch deposition run. The exit area of the substrate was cleaner than in the previous two runs, and a significant amount of coating was deposited in this area. The coating at the entrance end of the nozzle was too thin to be measured. An increase of 38 percent in the deposition rate occurred in the throat area which was much higher than the concentration increase of the methane indicating that the changes in deposition chamber geometry caused most of the increase.

Run S300-4 was conducted at a 20 percent higher total deposition gas flow rate than the previous run. The methane concentration was essentially unchanged. No changes were made in the deposition chamber geometry (Figure 43). Post-deposition examination of the coated nozzle showed the surface at the entrance end to contain several hard flowerlike carbon growths. From the throat to the exit end, the coating surface was covered with sooty deposits that had built upward from the gas exhaust section. The annular gas exhaust section and the gas exhaust ports in the mandrel were plugged with hard carbon deposits. The deposition rate in the throat area increased by nearly 42 percent.

Run 8300-5 was conducted using the same gas flow rates as the previous run. The deposition chamber geometry (Figure 44) was modified by using the 10.6-inch nozzle mandrel instead of the mandrel originally designed for 13-inch deposition runs. This modification increased the annular gap of the exhaust section from 1/4 inch to nearly 2 inches. Post-deposition examination of the coating showed the entrance end to contain scattered flowerlike carbon growths. The coating from the throat to the exit end was clean and free of any irregularities. There was no indication of clogging in the exhaust section demonstrating the effectiveness of the increased annular gap in preventing sooting in this area. There were, however, extensive deposits within the mandrel gas exhaust ports which may have forced termination of the run had a longer deposition run been attempted. The deposition rate in the groat area decreased by 36 percent as a result of the increased cross-sectional area between the mandrel and the substrate.




Figure 42. Deposition Chamber Geometry of Run No. 8300-2.




Figure 43. Deposition Chamber Geometry of Run No's. 8300-3 and 8300-4.




Figure 44. Deposition Chamber Geometry of Run No. 8300-5.

Run 8300-6 was conducted using the same process conditions as the previous run. The deposition chamber geometry (Figure 45) was changed by using a modified 13-inch mandrel with a reduced major diameter. This changed the annular gap of the exhaust section to one inch. The change was made to increase the PG deposition rate on the nozzle substrate while still maintaining enough gap in the exhaust section to prevent clogging. Post-deposition examination showed the coating at the entrance end to contain scattered flowerlike carbon growths as in past runs. No sooting was evident in the exhaust section except for the mandrel exhaust ports. The PG deposition rate had increased by 43 percent in the throat area but remained the same at the exit end.

Run 8300-7 was conducted using a 7 percent higher nitrogen rate and a 13 percent lower methane concentration. The methane concentration was reduced in an attempt to reduce the formation of the sooty, flowerlike growths which had been occurring at the entrance end. The deposition chamber geometry (Figure 45) was unchanged. Post-deposition examination showed the coating surface to be free of irregularities with the exception of the extreme entrance end. A narrow annular ring of deposits had formed in this area. These would normally be removed when the 100 mil trim was made. The exhaust section of the deposition chamber was free of soot with the exception of the mandrel exhaust ports which were nearly filled with soft deposits. The deposition rate decreased by 23 percent at the throat and 33 percent at the exit end.

Run 8300-8 was conducted using the same gas flow rates and deposition chamber geometry (Figure 45) as the previous run. The deposition time was extended to eight hours to obtain a 60-mil coating thickness. Post-deposition examination showed the entrance approach section of the deposition chamber and the entrance end of the substrate to be sprinkled with several hard, flowerlike carbon growths. The gas exhaust ports in the mandrel were plugged with hard, sooty deposits. No thickness measurements could be obtained at the nozzle coating ends because extensive, clinkerlike carbon growths had accumulated in these areas. The coating deposition rate in the throat area increased by slightly less than 10 percent.

Run 8300-9 was conducted using the same gas flow rates as the previous run. An aerodynamically contoured entrance approach section was utilized, and the mandrel exhaust ports were rounded to streamline the gas flow through the deposition chamber. The deposition chamber geometry is shown in Figure 46. Neither of the changes proved to be effective. After 4 hours and 50 minutes of deposition time, the mandrel exhaust ports clogged forcing termination of the run. Post-deposition examination showed the entrance approach area and the nozzle entrance and to be sprinkled with many hard, flowerlike growths. The deposition rate increased by 18 percent in the throat area, Very little measurable coating was obtained at the exit end.

Run 8300-10 was conducted using a deposition chamber geometry similar to that of the previous run except the mandrel was eliminated. The geometry is shown in Figure 47. The gas flow rates were the same as those of the previous run. Post-deposition examination showed the absence of the mandrel to have eliminated the flowerlike carbon growths in the upstream area of the deposition chamber. The nozzle coating was clean except for a narrow annular ring of growths at both the entrance and exit ends. The absence of a mandrel caused a drop of 45 percent in the deposition rate at the throat. The deposition rates at the ends were too low in proportion to that of the throat area. The gas exhaust area of the deposition chamber was clean, indicating that longer deposition times were possible.




Figure 45. Deposition Chamber Geometry of Run No's. 8300-6, 8300-7 and 8300-8.




Figure 46. Deposition Chamber Geometry of Run No. 8300-9.




Figure 47. Deposition Chamber Geometry of Run No. 8300-10.

Run 8300-11 was conducted utilizing the same gas flow rates as the previous run. The injector was lowered 1/4 inch; otherwise, the deposition chamber geometry (see Figure 48) was the same as that of the previous run. The deposition time was increased to increase the coating thickness. Post-deposition examination showed a throat coating thickness of 68 mils, which was near the desired thickness. The deposition rate at the throat had increased by 22 percent. A 1/4-inch-wide annular ring of growths had formed around the entrance end of the nozzle. A similar band of growths, 1/2 inch wide, had also formed at the exit end. These rings masked the substrate at the ends, causing a substantial reduction of the coating thickness in these areas. Also contained within the coating was a single flowerlike growth halfway between the entrance end and the throat. The furnace gas exhaust tube liner had partially clogged during the run and this was thought to have caused soot to blow back into the deposition chamber. The liner was removed for the following run to prevent this problen.

Run 8300-12, the last of the 13.0-inch series, was onducted utilizing the same gas flow rates and deposition chamber geometry (Figure 48) as the previous run. It was to have been 11 hours in duration but was aborted after 6 hours because the brickwork in the furnace gas exhaust section overheated. Post-deposition examination showed the coating to be covered with small flowerlike carbon growths. These had just started to form and were probably related to the failure of the exhaust section of the furnace. Annular rings of carbon growths had started to form at the entrance and exit ends.

4. 12.45-INCH NOZZLE THROAT INSERTS

Fourteen 12.45-inch throat diameter nozzle insert fabrication runs were conducted. Because of the similarity of the two substrates, the 12.45-inch deposition runs should be considered a continuation of the 13.0-inch series.

A typical 12.45-inch throat insert is shown in Figure 49. Typical microstructures, observed at the coating ends, are shown in Figures 50 and 51.

Deposition conditions are shown in Table IX. Coating and substrate data are shown in Table X.

Before this series of runs was undertaken, the furnace susceptor length was increased from 10 to 15 inches. This permitted the deposition chamber geometry to be lengthened to obtain an increased injector standoff distance and reduced the angle of impingement of the deposition gas on the substrate surface. These modifications were necessitated by the increased substrate length and the high degree of wraparound at the substrate entrance end. The greater injector standoff allowed the gas come to expand fully and completely enclose the substrate surface. The mandrel body was mounted on four 1/2-inch-diameter graphite pegs. This maximized the gas exhaust area and eliminated the clogging problem which occurred during the 13.0-inch deposition series.

The injector tip configuration for Runs 8300-13 through 8300-18 is shown in Figure 52. Figure 53 shows the configuration utilized for Runs 8300-19 through 8300-26.




Figure 48. Deposition Chamber Geometry Run No's. 8300-11 and 8300-12.




Figure 49. 12.45-inch Throat Insert No. 8300-24, Entrance End View.



Figure 50. Coating Microstructure of 12.45-inch Insert No. 8300-21, Entrance End, 60X.




Figure 51. Coating Microstructure of 12.45-inch Insert No. 8300-21, Exit End, 60X

79

Table IX. 12.45-inch Nozzie Throat Insert Deposition Conditions.

Run Ident No.	Log Book No.	Annulus N ₂ (SCFH)	Process N ₂ (SCFH)	CH ₄ (SCFH)	Volume Percent CH4	Dep. Temp. (°F)	Dep. Time (hr)	Remarks
8300-13	009-27	100	960	30	2.8	3950	3.00	Pilot run utilizing 12.45-in. insert design. High N ₂ rate and low CN ₃ concentration utilized to minimize sooting in gas stream.
8300-14	009-28	100	960	30	2.8	3950	3.00	Large mandrel utilized to reduce annular area of deposition chamber. Mandrel set on four 1/2-inch diameter posts to increase gas exhaust area.
8300-15	009-30	100	960	30	2.8	3950	3.00	Utilized same configuration as 8300-13 with no mandrel
8300-16	009-31	100	1440	30	1.9	3950	3.00	Reinstalled mandrel from run 8300-13 to increase deposition rate. Increased Ng process rate to reduce sooting in gas stream.
8300-17	009-32	100	1200	30	2.3	3950	4.50	Reinstalled shortened mandrel from run 8300-14 to incresse deposition rate. Process Ng rate reduced.
8300-18	009-33	100	1200	30	2.3	3950	8.00	Generator shut-off at 4.5 hours causing a temporaty reduction of 900°F in the deposition temperature
8300-19	009-34	100	1200	30	2.3	3950	8.00	Mandrel lowered 1/4 inch to increase deposition rate at downstream end a substrate. New injector tip with smaller orifices utilized.
8300-20	009-36	100	1452	30	1.9	3950	8.00	Increased process No rate to reduce sooting in gas stream.
8300-21	009-38	100	1452	30	1.9	4100- 4350	0.50	Deposition temperature increased to to increase coating density. Temperature also increased, during deposition to compensate for insulating effect of coating.
8300-22	009-42	100	1452	30	1.0	4100- 4200	7.00	Mendrel raised in chamber in an attempt to increase the deposition rate at substrate exit end.
8300-23	009-45	100	1452	40	1.9	4100- 4200	4.17	Mandrel appeared to be shading aft and of substrate so it was lowered.
8300-24	009-49	100	1452	30	1.9	4100- 4200	8.50	Substrate raised 1/2-inch, in deposition chamber, to increase deposition rate at exit end.
8300-25	009-50	100	1452	39	2.5	4100- 4200	7.10	CH ₄ rate increased to increase deposition rate.
8300-26	009-51	100	1452	39	2,5	4150 (Avg.)	4.00	Injector lowered 1/4 inch. Ges exhaust tube plugged at 4 hours.

Table X. 12.45-inch Nozzle Throat Insert Substrate and Coating Data.

e de	Los Book	Substrate	trate	Coating	Coating Thickness (in)	(in)	Deposition Rate (mils/hr)	n Rate (mi	its/hr)	
sent. No.	Ž.	Material	Configuration	Entrance	Throat	Exit	Entrance	Throat	Exit	Appearance
300-13	009-27	AGSR-VCG (surface treated)	-	NE	4.014	NE	1	£.4	1	Entire deposition chamber inner surface covered by clinkers and flower-like carbon growths.
300-14	009-28	Reused above part	_	NE®	0.016	NE.	I	5.3	ı	Entire mandrel surface covered with sooty deposits. Forward and of substrate covered with clinkers. Exit and rough and irregular.
:300-15	009-30	Reused above part	-	NE.	0.010	NE.	1	3.3	ı	Coating covered with flower-like carbon growths.
1300-16	1009-31	Reused above part		510.0	0.014	0.015	5.0	4.7	5.0	Coating free of surrace oxfects. End thicknesses are very difficult to determine and may be in error by 50 percent.
.300-17	009-32	Reused above part.	-	0.033	0.032	0.029	7.3	7.1	7.9	Coating free of surface defects.
1300-18	009 -33	Reused above part		0.055	0.059	0.034	6.9	7.4	4.3	Coating surface free of defects. Coating debaninated where deposition temperature fell about midway through run.
3300-19	009-34	AGSR-VCG (surface treated)	-	190.0	090.0	0.042	1.7	5.7	5.3	Coating gray in color and somewhat rough in surface texture. Entrance and delaminated severy during machining.
1300-20	009-36	Reused 8300-18 substrate	·	0.057	0.050	0.039	1.7	6.3	6.4	Coating gray in color and slightly smoother than 009-34. No major defects. Some intraconical dehaminations vivible. Sent to TRW. Coating density somewhat less than 2.20 (2.15 - 2.20)
:300-21	98-38	AGSR-VCG (surface treated)	-	0.060	0.061	0.040	7.1	7.2	4.7	Costing contains several nodules about 1/16 inch diameter between entrance end and throat. Costing black in color. No significant delaminations visible.
3300-22	009-42	AGSR-VCG/ Annealed (surface treated)	₹	0.043	0.049	0.026	1.	7.0	3.7	Coating surface appearance is good. Ends show no ignificant cracks or delaminations. A few large growth cones contain occasional intraconical delaminations. Sent to TRW.
8300-23	009-45	AGSR-VCG/ Annealed (surface treated)	81	0.025	0.029	0.012	6.0	7.0	2.9	Coating surface appearance is very good. Coating ends similar in appearance to No. 009-42.
8300-24	009-49	AGSR-VCG/ Annealed (surface treated)	5 1	0.05	0.055	0.054		3	3	No significant flaws.
8300-25	069-50	AGSR-VCG/ Annealed (surface treated)	ភ	0.058	0.065	0.057	2		9	Two longitudinal cracks in coating inner surface at chaining from entrance to exit end. Ends of these cracks radiate into circumferential determinations at both ends. Coating surface rough in texture and gray in color.
8300-26	009-51	AGSR-VCG/ Annealed (surface treated)	2	0.023	0.033	0.033	9	£.	e.	No examination of coating ends. Coating surface rough in texture and gray in color.

*Not E.camined




Figure 52. Injector Tip Configuration Utilized for Runs 8300-13 thru 8300-15 (Plenum diameter 0.343) and Runs 8300-16 thru 8300-18 (Plenum diameter as shown).




Figure 53. Injector Tip Configuration Utilized for Runs 8300-19 thru 8300-26.

The substrate inner contour was the same for all fourteen runs and is shown in Figure 54. Also shown are the various stress-relief groove modifications which were utilized. The substrate outside diameter was 16.550 inches for Runs 8300-13 through 8300-22. The substrate outside diameter was reduced to 15.550 inches for Runs 8300-23 through 8300-26 to allow the substrate to yield during cooldown and, therefore, relieve some of the stresses induced within the coating because of substrate/coating CTE mismatch.

Substrate dimensions were recorded before and after deposition for Runs 8300-22, 8300-23, 8300-25 and 8300-26 to determine how much deformation of the substrates occurred after cooldown. These data are summarized in Table XI. Although the data is fragmentary, there was in all cases a definite expansion of the substrate outside diameter after coating. The magnitude of these deformations is indicative of the severe stresses which exist in both coating and substrate after cooldown. The data from the length measurements is too fragmentary to be meaningful.

Run 8300-13, the first of the 12.45-inch series, was conducted utilizing a total gas flow rate 29 percent higher than that of the latter 13.0-inch deposition runs. The methane concentration was, however, reduced by 28 percent. The higher flow rates and lower methane concentration were an attempt to reduce sooting within the gas phase, which was the primary cause of the clinkerlike growths and other similar aberrations which occurred in the 13.0-inch series. The deposition chamber geometry is shown in Figure 55. Post-deposition examination showed the entire deposition chamber to be covered with flowerlike carbon growths. The coating at the nozzle ends was too thin to be measurable.

Run 8300-14 was conducted using the same gas flow rates as the previous run. A much larger mandrel was utilized to reduce the free-volume within the deposition chamber. The deposition chamber geometry is shown in Figure 56. Post-deposition examination showed the deposition chamber to be covered with flowerlike carbon growths. There was significantly more sooting than in the previous run.

Run 8300-15 was conducted using the same gas flow rates as the previous two 12.45-inch deposition runs. The deposition chamber geometry was the same as that of Run 8300-13 (see Figure 55), except the mandrel was removed. Post-deposition examination showed the entire inner surface of the deposition chamber to be covered with flowerlike carbon growths. An examination of the injector tip showed the gas flow rate through five adjacent ports to be considerably lower than that of the other eleven. This condition caused an area of gas recirculation within the deposition chamber and probably contributed to the excessive sooting encountered during this and the previous two 12.45-inch deposition runs.

Run 8300-16 was conducted utilizing a 50 percent higher process nitrogen flow rate than that of the previous run. The deposition chamber geometry was the same as that of Run 8300-13 (see Figure 55), during which the smaller of the two 12.45-inch mandrels was used. The injector tip plenum was enlarged to correct the problem of unequal flow rates which was discovered after the previous run. Post-deposition examination showed the deposition chamber to be completely free of the type of abnormal growths encountered in the three previous 12.45-inch runs. The nozzle coating was smooth, and the thickness distribution was acceptable. The deposition rate was lower than desired, and the objective of the next fabrication run was to increase this rate.




Figure 54. 12.45-inch Nozzle Throat Insert Substrate Configuration 1 (Including groove modifications).

Table XI. 12.45-inch Nozzle Throat Insert Substrate Dimensional Data.

Run Ident No.	Log Book No.	Substrate Material	Entrance OD	Throat OD	Exit OD	Length
8300-22	009-42	AGSR-VCG (Annealed)	0.20	0.15	0.14	_
8300-23	009-45		0.19	0.11	0.10	_
8300-25	009-50		0.14	_	0.10	0
8300-26	009-51	•	0.14		0.10	80.0
Averag	je		0.17	0.13	0.11	0.04




Figure 55. Deposition Chamber Geometry of Run No's. 8300-13, 8300-15 (Mandrel removed) and 8300-16.




Figure 56. Deposition Chamber Geometry of Run No. 8300-14.

Run 8300-17 was conducted using a process nitrogen flow rate midway between that of Runs 8300-15 and 8300-16. The methane rate was unchanged, which effectively increased the concentration by 21 percent. The larger of the two 12.45-inch mandrels was shortened by 1.5 inches at the tip and installed to increase the deposition rate. The deposition chamber geometry is shown in Figure 57. Post-deposition examination showed the deposition chamber to be free of any abnormal deposits. The nozzle coating was smooth and free of surface defects and the gas exhaust area was clean. The deposition rate increased by 46 percent at the entrance end, 51 percent at the throat and 28 percent at the exit end.

Run 8300-18 was conducted utilizing the same gas flow rates and deposition chamber geometry (Figure 57) as the previous run with one slight modification; the injector was moved 0.25 inch closer to the nozzle substrate. After 4 1/2 hours of deposition, the power to the furnace was interrupted by a loss of water pressure in the motor generator. The deposition temperature dropped to 3050°F at this time, and approximately 1 1/2 hours were required for the furnace to regain the desired temperature. Post-deposition examination showed the deposition chamber to be free of any abnormal carbon growths, and the surface appearance of the nozzle coating was good. The drop in temperature caused a line of renucleation within the coating, and as a result the coating delaminated in this area. The coating deposition rate decreased by 5 percent at the entrance end and increased by 4 percent at the throat. The rate at the exit end decreased by 33 percent.

Run 8300-19 was conducted utilizing the same deposition gas flow rates as the previous two runs. The mandrel was lowered 1/4 inch to increase the deposition rate at the exit end. The deposition chamber geometry is shown in Figure 58. A new injector tip was fabricated (see Figure 53) with reduced orifice diameters to increase the pressure in the plenum and stabilize the flow rate through the individual gas ports. Post-deposition examination showed the coating to be gray in color and to have a somewhat rough surface texture; the microstructure showed large cone angles. The coating at the entrance end delaminated extensively during the trimming operation. The deposition rate increased by 12 percent at the entrance end, 1 percent at the throat and 23 percent at the exit end.

Run 8300-20 was conducted utilizing a process nitrogen rate slightly higher than 8300-16. This represented an increase of 21 percent over the process nitrogen rate of the previous run. Other process conditions were the same as those of the previous run. The mandrel was moved up 1/4 inch in the deposition chamber; otherwise, the geometry was like that of the previous run (see Figure 58). These changes were made in an attempt to improve the coating microstructure and surface condition which had deteriorated in the previous run. Post-deposition examination showed the coating surface to be similar to that of 8300-19. No significant defects were visible in the polished coating ends. The coating microstructure was somewhat improved over that of 8300-19 but was still not acceptable. The density of the coating was determined to be less than 2.20 g/cc, using the sink/float technique, indicating that the deposition temperature was too low. An overall decrease in deposition rate occurred because of the reduced methane concentration in the process gas.

Run 8300-21 was conducted at an increased deposition temperature. The temperature at the beginning of the cycle was 4100°F. The deposition temperature was to have been slowly increased 400°F during the run. However, full power was reached at six hours, at which time a 250°F temperature increase was achieved. From that time, the temperature readings declined slowly to 4200°F at which time deposition was terminated. The general increase in deposition temperature was utilized to increase the coating density and to improve the coating microstructure. The temperature increase during ucposition was to maintain the surface temperature of the coating




Figure 57. Deposition Chamber Geometry of Run No's. 8300-17 and 3300-18 (Injector lowered 1/4 inch).




Figure 58. Deposition Chamber Geometry of Run No's 8300-19 (Mandrel position Indicated by broken line),8300-20 and 8300-21.

as the coating thickness increased. The deposition gas flow rates and the deposition chamber geometry (Figure 58) were the same as those of the previous run. Post-deposition examination showed the coating to be of acceptable quality with the exception of several large nodules at the entrance end. These nodules appeared to have started early in the cycle and were all about the same size. Microscopic examination of the coating ends showed no major cracks or delaminations. The coating deposition rate increased by 14 percent at the throat and decreased by 4 percent at the exit end. No change occurred at the entrance end.

Run 8300-22 was conducted utilizing the same deposition gas flow rates as the previous run. The mandrel body was raised 0.8 inch to fill some of the free-volume in the deposition chamber and increase the deposition rate of the coating. The deposition chamber geometry is shown in Figure 59. The deposition temperature was 4100°F at the beginning of the cycle and was increased, slowly and evenly, to 4200°F at termination. Post-deposition examination showed the coating surface texture to be very good. Microscopic examination of the polished coating ends showed no cracks or significant delaminations. There were a few large growth cones present which contained an occasional intraconical delamination. The coating thickness at the throat was less than the desired 60 mils. The deposition rate decreased by 14 percent at the entrance end, 3 percent at the throat and 21 percent at the exit end. Apparently the mandrel was deflecting the gas, from the substrate, causing an overall reduction in the deposition rate.

Run 8300-23 was conducted for 4 hours and 10 minutes. The planned time was 8 1/2 hours, but a malfunction of the methane regulator caused a severe drop in the flow rate and deposition had to be terminated prematurely. The deposition chamber geometry (Figure 60) was the same as that of the previous run except the mandrel body was lowered 3/8 inch. The deposition gas flow rates were the same as those of the previous run. Post-deposition examination showed the coating surface appearance to be very good. Microscopic examination of the polished coated ends indicated that the coating structure was the same as that of the previous 12.46-inch nozzle. The deposition rates at the entrance end and the throat were essentially unchanged. However, the rate at the exit end had declined by 22 percent and, consequently, the exit end coating was much thinner than desired.

Run 8300-24 was conducted using the same gas flow rates as the past several runs. The stress relief grooves in the substrate ends conformed to the dimensions established by the stress analysis groove optimization studies for the 7-inch size (see Volume II). The substrate was raised 0.5 inch in the deposition chamber to increase the coating deposition rate at the exit end. The deposition chamber geometry is shown in Figure 61. Post-deposition examination showed the coating surface quality to be very good. The coating thickness distribution was satisfactory with a variation of only 4 mils from entrance to exit end. Microscopic examination of the polished coating ends showed a good renucleated structure with only an occasional large growth cone containing intraconical delaminations. No significant cracks or delaminations were visible at either end.

Run 8300-25 was conducted at a 32 percent higher methane concentration than that of the previous run in an attempt to increase the coating deposition rate. The remaining deposition gas flow rates and the deposition chamber geometry (Figure 61) were the same as those of the previous run. During deposition the furnace rotator stopped twice. The second time the furnace power had to be interrupted long enough to replace the rotator motor;




Figure 59. Deposition Chamber Geometry of Run No. 8300-22.





Figure 60. Deposition Chamber Geometry of Run No. 8300-23.



.Figure 61. Deposition Chamber Geometry of Run No's. 8300-24, 8300-25 and 8300-26 (Injector lowered 1/4 Inch).

as a result, the deposition temperature dropped 400°F. Post-deposition examination showed the coating to be gray in color and rather rough in texture. The coating inner surface contained two longitudinal cracks extending from the entrance to the exit end. At the coating ends these cracks radiated into circumferential delaminations within the coating. These coating defects were a direct result of the extreme drop in the deposition temperature and, with the possible exception of the coating roughness, would not have occurred if the deposition temperature had remained at the desired level. The coating deposition rate increased by 21 percent at the entrance end, 42 percent at the throat and 25 percent at the exit end.

Run 8300-26, the last of the 12.45-inch series, was conducted using the same deposition gas flow rates as the previous run and for the same purpose. The deposition chamber geometry (Figure 61) was unchanged with the exception of the injector which was lowered 1/4 inch. After four hours of deposition, the gas exhaust tube clogged and forced termination of the run. Post-deposition examination showed the coating to be rough and gray in color. The appearance indicated that the deposition temperature was too low. The coating deposition rate decreased by 29 percent at the entrance end and 10 percent at the throat and increased by 4 percent at the exit end.

SECTION VII

DISCUSSION

Nominal deposition parameters were established for all three nozzle throat insert sizes. These are shown in Table XII.

The last fourteen 7.0-inch deposition runs were conducted using similar process conditions and the same deposition chamber geometry. The standard deviation of the coating deposition rate was calculated at the entrance, throat and exit planes for these runs and is included in Table XII. This variation was acceptable considering that no significant effort was expended in achieving more uniform rates, and the fact that these 14 runs were conducted over a time span of 11 months.

Although the last of the three 10.6-inch deposition runs did yield a marginally acceptable coating, the deposition conditions utilized were not considered to be optimum. An increase in the process nitrogen rate on the order of 50 to 100 percent would be expected to yield coatings with a more uniform coating thickness profile. Such an increase would have been utilized had additional runs been conducted at this size.

The parameters used for Run 8300-24 were quite suitable for the 12.45-inch size. Although the deposition rates were somewhat lower than desired, they would be considered acceptable unless very thick coatings and, therefore, longer deposition times were required.

The various deposition chamber geometries used for large nozzle deposition runs indicate that the deposition rate is increased significantly by the utilization of a mandrel body in the center of the deposition chamber. In those cases where a mandrel was not used, the coating deposition rate and proportional thickness at the ends were both severely reduced.

The injector tip configuration was established by utilizing the fact that a turbulent gas jet expands from an orifice at an included angle of 20 degrees. The injector orifices were angled toward the substrate and the injector was positioned so that the expanding gas cone completely enveloped the substrate surface. Nozzle substrates, coated with the injector tip located so near the part that the gas cone could not expand fully, had an excessive deposition rate in the area of impingement and, as a result, these parts had an unacceptable coating thickness profile.

Process nitrogen flow rates were established as a function of the amount of sooting in the gas phase. In general, if the inside surface of the deposition chamber was found to contain soot or carbon growths, an increase in the process nitrogen rate was used to eliminate the problem. Increasing the gas flow rate reduces the deposition gas temperature by reducing the dwell time in the chamber. This prevents the formation of soot particles in the gas phase which, if present, lodge on the coating surface forming nuclei for flowerlike carbon growths and large nodules.

Table XII. Nominal Process Conditions for Large Nozzle Deposition Runs.

	Deposition Chamber Geometry	Figure 35		Figure 39	Figure 61
(mils/hr)	At Exit	7.9	9.0	5.4	€.4
osition Rate	At Throat	10.2	0.7 0.6	10.8	6.5
Expected Dep	At At At Entrance Throat Exit	9.3	0.8	8.0	89
CH.	Concentration (volume percent)	2.5	Standard Deviation	4.5	6.1
Process	Nitrogen Rate (SCFH)	480	Standar	448	1452
Annulus	Nitrogen Rate (SCFH)	100		80	100
Nozzle	Throat Insert Code	6300ª		7300 ^b	8300c

^aData derived from last 14 deposition runs. ^bData derived from Run No. 7300-3. ^cData derived from Run No. 8300-24.

Although coatings up to 60 mils in thickness readily survived the deposition cycle, they did not survive during the 7.0-inch nozzle throat insert test firings (see Volume I). The expansion of the substrate outrage diameters after deposition indicates that AGSR is not a particularly good substrate material for large diameter coated parts. A substrate material with a hoop direction CTE similar to that of PG in the "ab" plane would yield a system with greatly reduced stress levels, both in the coating and the substrate, and increase their likelihood of surviving the firing cycle.